

---

## 2GIG Go!Control Firmware Release Notes

### Firmware Version 1.10.1

This document provides the details of the 1.10.1 Firmware release from 2GIG Technologies security panels.

#### Contents

- Introduction
- New in Release 1.10.1
- Summary of past firmware releases
- Limitations and Special Instructions (**PLEASE READ BEFORE UPDATING TO 1.10.1**)

#### Introduction

In an effort to provide continual improvement and increased quality a new version of firmware has been released, version 1.10.1 for the Go!Control. The following enhancements are included in this release:

- Telguard Online support

#### New in Release 1.10.1

The following sections describe in detail the enhancements and modifications to the Go!Control operational firmware and configuration options.

- Support for the 2GIG-GC3GA-T 3G cell radio and associated Telguard remote services.
- A fix for the scenario where Z-Wave lock codes were being removed after system configuration change.
- Minor Spanish language corrections.

#### Summary of past firmware releases

The following section provides a list of enhancements included in past firmware releases. For more detailed information on the enhancements in these releases, go to the 2GIG dealer web site at [www.2gig.com](http://www.2gig.com) and click on the "Release Notes - Technical Bulletins" link under the "Support" section.

#### Release 1.10

- Image Sensor support
- Schlage lock support

## Release 1.9.6

- Support for CDMA radios

## Release 1.9.5

- CDMA Cell Radio Support
- POTS Line Seizure Improvements
- Dealer Control of Backlight Feature

## Release 1.9.2

- Mute Audio When Idle
- Cell Radio Reliability on Battery Backup
- Manufacturability Enhancements

## Release 1.9

- Support for 32 users
- Spanish language support
- Ready to Arm Behavioral Change
- Additional Z-Wave door lock support (Schlage and Yale)
- Z-Wave siren support (Everspring and FortrezZ)
- Improved user experience for Z-Wave devices
- Silent arming
- Redundant clock widget removed
- 4 additional chimes added
- Additional vocabulary support

## Release 1.8

- Support for 2GIG's new Wireless Touch Screen Keypad (2GIG-TS1)
- Usability improvements to security functions
- Silent arming
- Backlight off
- Z-Wave usability improvements and enhanced features
- Additional configuration parameters for the installer
- Availability of Canadian-French localized panels

## 2GIG Go!Control

V1.10.1 Firmware Release Notes

Date 09-13-2013



---

## Limitations and Special Instructions

### **IMPORTANT: PLEASE READ THESE INSTRUCTIONS BEFORE UPDATING TO RELEASE 1.10.1**

A Go!Control Panel running 1.10.1 can only be paired to a TS1 keypad at revision 1.10 or higher. A TS1 with 1.9.6 or lower firmware cannot be updated using an over-the-air (OTA) firmware update when learned into a panel with 1.10.1 firmware and must be manually upgraded by using the firmware update cable (2GIG-UPCBL1) to 1.10 firmware revision.

The Go!Control Panel and TS1 Firmware Update Tool and instructions are posted on the 2GIG dealer web site at [www.2GIG.com](http://www.2GIG.com) under the Firmware Update Tool menu.

Note: When using the update cable to update a TS1, the cable must now be connected directly to the TS1 device using a 4-pin header.

## 2GIG Technical Support

### **For technical support in the USA and Canada:**

855-2GIG-TECH (855-244-4832)

Email: [techsupport@2gig.com](mailto:techsupport@2gig.com)

Internet: [dealer.2gig.com](http://dealer.2gig.com)

Visit [dealer.2gig.com](http://dealer.2gig.com) for technical support hours of operation

### **For technical support outside of the USA and Canada:**

Contact your regional distributor

Visit [dealer.2gig.com](http://dealer.2gig.com) for a list of distributors in your region